

TECHNICAL CIRCULAR No. 460 of 08th January 2018

То:		All Surveyors/Auditors	
Applicab	ole to flag:	All Flags	
	Deck str	ructure inspection-3, Under-deck inspection	
Reference:	CONARI	NA class	

Deck structure inspection-3 Under-deck inspection

3 What to look for - Under-deck inspection

3.1 Material wastage

- **3.1.1** The level of wastage of under-deck stiffeners/structures may have to be established by means of thickness measurements. As mentioned previously the combination of the effects from the marine environment and the local
- atmosphere will give rise to high corrosion rates.
- **3.1.2** Severe corrosion of the hatch coaming from inside and of under deck girders may occur due to difficult access for maintenance of the protective coating.

This may in turn lead to fractures.

3.2 Deformations

3.2.1 Buckling should be looked for in the primary supporting structure, e.g. hatch end beams and longitudinal girders beneath the longitudinal hatch coamings, if sagging of deck panels has been observed during on-deck inspection. Such buckling may also be the initial observation of damage caused by lateral overloading because of excessive deck cargo, improper distribution/support of deck cargoes, sea water on deck in heavy

weather, or a combination of these causes.

3.3 Fractures

- **3.3.1** Fractures in the connection between the transverse bulkheads, girders/stiffeners and the deck plating may occur. This is often associated with a reduction in area of the connection due to corrosion.
- **3.3.2** Fractures in the primary supporting structure, e.g. hatch end beams may be found in the weld connections at the ends of the beams/girders.

Customer Service Center
5201 Blue Lagoon Drive, 9TH. Floor,
Miami, Fl., 33126
Tel: 1 (305) 716 4116,
Fax: 1 (305) 716 4117,
E-Mail:

joel@conarinagroup.com

Technical Head Office 7111 Dekadine Ct. Spring, Tx., 77379 Tel: 1 (832) 451 0185, 1 (713) 204 6380

E-Mail: cbozenovici@vcmaritime.com

REFERENCES:

- CONARINA class
- ATTACHMENTS: No.

Kindest Regards, Cosmin Bozenovici Naval Architect – Conarina Technical Head Office

Customer Service Center
5201 Blue Lagoon Drive, 9TH. Floor,
Miami, Fl., 33126
Tel: 1 (305) 716 4116,
Fax: 1 (305) 716 4117,
E-Mail:

joel@conarinagroup.com

Technical Head Office 7111 Dekadine Ct. Spring, Tx., 77379 Tel: 1 (832) 451 0185, 1 (713) 204 6380

E-Mail: cbozenovici@vcmaritime.com