



TECHNICAL CIRCULAR No. 705 of 5th November 2021

To	All Surveyors/Auditors. All flags
Title	Docking survey
Reference	CONARINA Inspection to Surveyor

Drydock survey- Update

There is to be a minimum of two examinations of the outside of a vessel's bottom and related items during each five-year special survey period. One such examination is to be carried out in conjunction with the Special Periodical Survey.

In all cases, the interval between any two such examinations is not to exceed **36** months. For vessels not subject to SOLAS (GT<500) operating solely in fresh water, the maximum interval is not to exceed **five** years.

Visible parts of the propeller

Each propeller hub with greater than 10 years of service life is to be examined by a surface crack-detection method at each out of the water drydocking.

Propeller Removal

Whenever the propeller is removed for any reason, the propeller hub is to be examined by a surface crack detection method after reinstallation.

REFERENCES:

- CONARINA Instruction to Surveyors

ATTACHMENTS: No

kindest Regards,
 CONARINA Technical Office

CONARINA Head Office

6505 Blue Lagoon Dr. Suite 455
 Miami, Fl., 33126
 Tel: 1 (786) 558 5288,
 Fax: 1 (786) 325 0200,
joel@conarinagroup.com