



TECHNICAL CIRCULAR No. 178 of 16<sup>th</sup> February 2014

To:	All Surveyors/Auditors
Applicable to flag:	All Flags
Subject:	AMSA Inspectors entering lifeboats
Reference	SOLAS Ch. III

**AMSA Inspectors entering lifeboats**

*The Australian Maritime Safety Authority AMSA has issued Marine Notice for inspectors entering lifeboats to draw their attention on relevant incidents and the use of additional restraints.*

The maritime industry has in recent years been aware of incidents occurring world-wide in relation to lifeboat release arrangements.

Predominately, Port State Control (PSC) and Flag State Control (FSC) detentions relating to this subject have been for defective maintenance of the equipment. This equipment is often designed in such a way that maintaining clearances between moving parts and proper maintenance to these lifeboats is absolutely critical.

AMSA notes that there has been a reduction in lifeboat accidents, which is likely due to improved awareness of the problem and the introduction of interim measures such as fall prevention devices. Further improvements in safety outcomes are anticipated from the more permanent measures being introduced, such as the replacement of on-load release mechanism that do not meet the current IMO standard. Replacement must be completed no later than the first scheduled dry-docking after 1 July 2014, but not later than 1 July 2019.

However, vigilance still needs to be maintained to prevent further lifeboat accidents.

As a result AMSA has instructed its inspectors that they should not rely on the boat harbor pins and gripes if an inspector is to enter a lifeboat - unless it can be demonstrated to the AMSA inspector that lifeboat release arrangements are correctly set. If this is unable to be demonstrated, additional restraints are required to be fitted.

The AMSA inspector will discuss such requirements with the master of the vessel early in a PSC or FSC inspection to avoid unnecessary delays. It is the responsibility of the master NOT the AMSA inspector to determine a suitable supplementary restraint arrangement, however, the AMSA inspector must be satisfied with the method used before entering the lifeboat.

This requirement is for entry into the lifeboat when fully housed ONLY. The arrangement is to be removed immediately upon completion of the lifeboat inspection and under NO circumstances is the

**Customer Service Center**

5201 Blue Lagoon Drive, 9<sup>TH</sup>. Floor,  
Miami, Fl., 33126  
Tel: 1 (305) 716 4116,  
Fax: 1 (305) 716 4117,  
E-Mail:

[joel@conarinagroup.com](mailto:joel@conarinagroup.com)

**Technical Head Office**

7111 Dekadine Ct.  
Spring, Tx., 77379  
Tel: 1 (281) 370 9363,  
1 (713) 204 6380

E-Mail: [tho@conarinagroup.com](mailto:tho@conarinagroup.com),

[houston@conarinagroup.com](mailto:houston@conarinagroup.com)

lifeboat to be swung out with the supplementary restraint fitted.  
This requirement is a control mechanism that AMSA has implemented to reduce the AMSA inspector's exposure to risk and the cooperation of all owners, operators and masters is appreciated.

REFERENCES:

- SOLAS Ch. III and Maritime Safety-AMSA

ATTACHMENTS: No.

Kindest Regards,

Cosmin Bozenovici  
Naval Architect – Conarina Technical Head Office

**Customer Service Center**

5201 Blue Lagoon Drive, 9<sup>TH</sup>. Floor,  
Miami, Fl., 33126  
Tel: 1 (305) 716 4116,  
Fax: 1 (305) 716 4117,  
E-Mail:

[joel@conarinagroup.com](mailto:joel@conarinagroup.com)

**Technical Head Office**

7111 Dekadine Ct.  
Spring, Tx., 77379  
Tel: 1 (281) 370 9363,  
1 (713) 204 6380

E-Mail: [tho@conarinagroup.com](mailto:tho@conarinagroup.com),

[houston@conarinagroup.com](mailto:houston@conarinagroup.com)

Page 2 of 2