

TECHNICAL CIRCULAR No. 296 of 14th October 2015

То:	All Surveyors/Auditors
Applicable to flag:	All Flags
Subject:	CONARINA Report Monitoring for ISM/ISPS
Reference:	CONARINA Procedures

CONARINA Report Monitoring for ISM/ISPS

The following deficiencies may be identified during the CONARINA Head Office review of ISM and ISPS auditor's report:

- 1. Missing or Incorrect Information
 - 01 Inaccurate credit date
 - 02 Audit not credited
 - 03 Incorrect closing paragraph
 - 04 Incorrect selection of attendance vs. non-attendance work order
 - 05 Incorrect task selection or description
 - Of Status of task incorrect (commenced vs. completed)
 - 07 Missing attachments
 - 08 Other
- 2. Check sheets
 - 01 Missing
 - 02 Inaccurate
 - 03 Incomplete
 - 04 Other

Customer Service Center

5201 Blue Lagoon Drive, 9TH. Floor, Miami, Fl., 33126 Tel: 1 (305) 716 4116, Fax: 1 (305) 716 4117,

E-Mail:

joel@conarinagroup.com

Technical Head Office 7111 Dekadine Ct. Spring, Tx., 77379 Tel: 1 (832) 451 0185, 1 (713) 204 6380

E-Mail: cbozenovici@vcmaritime.com

3. Certificates

- 01 Incorrect certificate
- 02 Incorrect dates
- 03 Incorrect term
- 04 Incomplete
- 05 Missing or incorrect comments & remarks
- 06 Imported certificate different from issued
- 07 Obsolete DOCs not removed or cancelled
- 08 Certificate withdrawn inappropriately
- 09 Other

REFERENCES:

- CONARINA Procedures

ATTACHMENTS: No.

Kindest Regards, Cosmin Bozenovici Naval Architect – Conarina Technical Head Office

Customer Service Center

5201 Blue Lagoon Drive, 9TH. Floor, Miami, Fl., 33126 Tel: 1 (305) 716 4116, Fax: 1 (305) 716 4117,

E-Mail:

joel@conarinagroup.com

Technical Head Office 7111 Dekadine Ct. Spring, Tx., 77379 Tel: 1 (832) 451 0185, 1 (713) 204 6380

E-Mail: cbozenovici@vcmaritime.com