



TECHNICAL CIRCULAR No. 367 of 02nd October 2016

To:	All Surveyors/Auditors
Applicable to flag:	All Flags
Subject:	Port State Control 2015
Reference:	Port State Control Results

Top PSC Deficiencies 2015

1. Main Engine	160
2. Lifeboats	122
3. Other Machinery	108
4. Auxiliary Engine	82
5. Other Fire Safety	66
6. Lights, shapes, & sound-signals	66
7. Charts	64
8. Emergency lighting, batteries and switches	58
9. Fire doors/openings in fire-resisting divisions	58
10. Fixed fire extinguishing installation	53
11. Fire Dampers	42

REFERENCES:

- **PSControl**

ATTACHMENTS: No.

Kindest Regards,
Cosmin Bozenovici
Naval Architect – Conarina Technical Head Office

Customer Service Center

5201 Blue Lagoon Drive, 9TH. Floor,
Miami, Fl., 33126
Tel: 1 (305) 716 4116,
Fax: 1 (305) 716 4117,
E-Mail:

joel@conarinagroup.com

Technical Head Office

7111 Dekadine Ct.
Spring, Tx., 77379
Tel: 1 (832) 451 0185,
1 (713) 204 6380

E-Mail: cbozenovici@vcmaritime.com