



TECHNICAL CIRCULAR No. 539 of 09th February 2019

To:	All Surveyors/Auditors
-----	------------------------

Applicable to flag:	All Flags
---------------------	-----------

Documentation on board- Hull survey	
--	--

Reference:	CONARINA Instructions
------------	-----------------------

Documentation on board- Hull survey

The following documentation is recommended to be placed on board and maintained and updated by the owner for the life of the ship in order to be readily available for the survey party.

1. Survey Report File: This file includes Reports of Surveys and Thickness Measurement Report.

2. Supporting Documents: It is recommended that the following additional documentation be placed on board, including any other information that will assist the inspection.

- (a) Main structural plans of cargo holds and ballast tanks,
- (b) Previous repair history
- (c) Cargo and ballast history,
- (d) Inspection and action taken by ship's personnel with reference to:
 - structural deterioration in general
 - leakages in bulkheads and piping
 - condition of coating or corrosion protection, if any

3. Prior to inspection, it is recommended that the documents on board the vessel be reviewed as a basis for the current survey.

*Customer Service Center
5201 Blue Lagoon Drive, 9TH. Floor,
Miami, Fl., 33126
Tel: 1 (305) 716 4116,
Fax: 1 (305) 716 4117,
E-Mail:*

joel@conarinagroup.com

*Technical Head Office
7111 Dekadine Ct.
Spring, Tx., 77379
Tel: 1 (832) 451 0185,
1 (713) 204 6380*

E-Mail: vbozenovici@vcmaritime.com

REFERENCES:

- CONARINA Instructions

- ATTACHMENTS: No

Kindest Regards,
Val Bozenovici
Naval Architect – Conarina Technical Director

*Customer Service Center
5201 Blue Lagoon Drive, 9TH. Floor,
Miami, Fl., 33126
Tel: 1 (305) 716 4116,
Fax: 1 (305) 716 4117,
E-Mail:*

joel@conarinagroup.com

*Technical Head Office
7111 Dekadine Ct.
Spring, Tx., 77379
Tel: 1 (832) 451 0185,
1 (713) 204 6380*

E-Mail: vbozenovici@vcmaritime.com