

TECHNICAL CIRCULAR No. 056 of 24th May 2012

To:	All Surveyors/Auditor
Applicable to flag:	All Flags
Subject:	Guidance for completing SUPPLEMENT TO IAPP CERTIFICATE
Reference:	POLLUTION – IAPP CERTIFICATE

Guidance for completing SUPPLEMENT TO INTERNATIONAL AIR POLLUTION PREVENTION CERTIFICATE (IAPP CERTIFICATE), section 2.2.1

Applicable to Marine diesel engines with a power output of more than 5,000 kW and a per cylinder displacement at or above 90 liters installed on ships constructed on or after 1 January 1990 but prior to 1 January 2000.

1. If IMO has not published through an MEPC circular the availability of an approved method (upgrade kit), the entire section should be completed as not applicable.

Approved Method exists	-	-	-	-
Approved Method not commercially available	-	-	-	-
Approved Method installed	-	-	-	-

2. For the approved methods for engines that have been published by IMO, the first option should be marked as applicable.

Customer Service Center
5201 Blue Lagoon Drive, 9TH. Floor,
Miami, Fl., 33126
Tel: 1 (305) 716 4116,
Fax: 1 (305) 716 4117,
E-Mail:

joel@conarinagroup.com

Technical Head Office 7111 Dekadine Ct. Spring, Tx., 77379 Tel: 1 (281) 370 9363, 1 (713) 204 6380

E-Mail: tho@conarinagroup.com, houston@conarinagroup.com,

Approved Method exists	X	X	X	X
Approved Method not commercially available	-	-	1	-
Approved Method installed	-	-	-	-

3. In the event the shipowner documents that the upgrade kit is not commercially available (e.g., is in back order), the first two options should be marked as applicable when the approved method has been published and the manufacturer has provided a general notification to industry or an individual notification to the shipowner that there have been delays on manufacturing/delivering the kit. The second step would be to open a comment with the due date of the next annual after the method is commercially available (The estimated availability date provided by the manufacturer should be used as the reference point to determine the due date of the open the comment).

Approved Method exists	X	X	X	X
Approved Method not commercially available	X	X	X	X
Approved Method installed	-	-	-	-

4. Finally, when the kit is installed, the options for "approved method exists" and "approved method installed" should be marked as applicable.

Approved Method exists	X	X	X	X
Approved Method not commercially available	-	-	-	-
Approved Method installed	X	X	X	X

REFERENCES:

IAPP

ATTACHMENTS: No.

Kindest Regards, Cosmin Bozenovici

Naval Architect - Conarina Technical Head Office

Customer Service Center
5201 Blue Lagoon Drive, 9TH. Floor,
Miami, Fl., 33126
Tel: 1 (305) 716 4116,
Fax: 1 (305) 716 4117,

E-Mail:

joel@conarinagroup.com

Technical Head Office 7111 Dekadine Ct. Spring, Tx., 77379 Tel: 1 (281) 370 9363, 1 (713) 204 6380

E-Mail: tho@conarinagroup.com, houston@conarinagroup.com