

## TECHNICAL CIRCULAR No. 181 of 12th March 2014

To:	All Surveyors/Auditors
Applicable to flag:	All Flags
Subject:	USCG Policy Letter on On-Load Release Mechanisms
Reference	SOLAS – Life-Saving Appliance (LSA) Code

## **USCG Policy Letter on On-Load Release Mechanisms**

The US Coast Guard (USCG) has issued a policy letter which provides guidance to assist US-flag shipowners and operators in complying with SOLAS amendments requiring all SOLAS ships, regardless of build date, to identify and replace existing on-load release mechanisms (release hooks) that do not comply with specific provisions of the International Life-Saving Appliances (LSA) Code with compliant release mechanisms no later than the next scheduled dry-docking after 1 July 2014 (but in any case before 1 July 2019).

## REFERENCES:

- SOLAS – Life-Saving Appliance (LSA) Code

ATTACHMENTS: No.

Kindest Regards,

Cosmin Bozenovici Naval Architect – Conarina Technical Head Office

## **Customer Service Center**

5201 Blue Lagoon Drive, 9<sup>TH</sup>. Floor, Miami, Fl., 33126 Tel: 1 (305) 716 4116, Fax: 1 (305) 716 4117,

E-Mail:

<u>joel@conarinagroup.com</u>

Technical Head Office 7111 Dekadine Ct. Spring, Tx., 77379 Tel: 1 (281) 370 9363, 1 (713) 204 6380

E-Mail: tho@conarinagroup.com, houston@conarinagroup.com Page 1 of 1