

TECHNICAL CIRCULAR No. 197 of 24th May 2014

To:	All Surveyors/Auditors
Applicable to flag:	All Flags
Subject:	New requirements for fire-fighters' outfit
Reference:	IMO Res. MSC. 338(91)

The 2014 amendments to SOLAS and the Fire Safety Systems (FSS) Code adopted by IMO Resolutions MSC.338(91) and MSC.339(91) will enter into force on 1 July, 2014, introducing revised and new requirements for fire-fighter's outfit breathing apparatus and two-way portable radiotelephone apparatuses, as follows:

Breathing apparatus

- Changes to SOLAS regulation II-2/10.10.1 and the FSS Code mean that: "Compressed air breathing apparatus shall be fitted with an audible alarm and a visual or other device which will alert the user before the volume of the air in the cylinder has been reduced to no less than 200 litres."
 - This applies to ship's constructed (keel laid) on or after 1 July, 2014. Ships constructed (keel laid) before 1 July, 2014 must comply no later than 1 July, 2019.
- 2. New SOLAS regulation II-2/15.2.2.6, relating to 'Onboard training and drills' requires that: "An onboard means of recharging breathing apparatus cylinders used during drills shall be provided or a suitable number of spare cylinders shall be carried on board to replace those used."

This applies to all ships on or after 1 July, 2014.

Two-way portable radiotelephone apparatuses

New SOLAS regulation II-2/10.10.4 requires that: "For ships constructed on or after 1 July 2014, a minimum of two two-way portable radiotelephone apparatus for each fire party for fire-fighter's communication shall be carried on board. Those two-way portable radiotelephone apparatus shall be

Customer Service Center

5201 Blue Lagoon Drive, 9TH. Floor, Miami, Fl., 33126 Tel: 1 (305) 716 4116, Fax: 1 (305) 716 4117, E-Mail:

E-Mail.

<u>joel@conarinagroup.com</u>

Technical Head Office 7111 Dekadine Ct. Spring, Tx., 77379 Tel: 1 (281) 370 9363, 1 (713) 204 6380

E-Mail: tho@conarinagroup.com, houston@conarinagroup.com Page 1 of 2 of an explosion-proof type or intrinsically safe. Ships constructed before 1 July, 2014 shall comply with the requirements of this paragraph not later than the first safety equipment survey after 1 July, 2018."



REFERENCES:

IMO Res. MSC. 338(91)

ATTACHMENTS: No.

Kindest Regards,

Cosmin Bozenovici Naval Architect - Conarina Technical Head Office

Customer Service Center

5201 Blue Lagoon Drive, 9TH. Floor, Miami, Fl., 33126 Tel: 1 (305) 716 4116, Fax: 1 (305) 716 4117,

E-Mail:

joel@conarinagroup.com

Technical Head Office 7111 Dekadine Ct. Spring, Tx., 77379 Tel: 1 (281) 370 9363,

1 (713) 204 6380

E-Mail: tho@conarinagroup.com, houston@conarinagroup.com Page 2 of 2