

TECHNICAL CIRCULAR No. 234 of 04th December 2014

| To: | All Surveyors/Auditors | |
|---------------------|----------------------------------|--|
| Applicable to flag: | All Flags | |
| Subject: | MLC Special Instruction (Panama) | |
| Reference: | MLC Panama | |

MLC Special Instruction

1. Panamanian ratification status of related ILO Conventions:

ILO C74 Ratified 4 June 1971 ILO C92 Ratified 4 June 1971

ILO C133 Not signatory

The Panamanian Administration has implemented Resolution No. VII wherein the following category of persons are exempt from the definition of seafarer. [MMC-265/(4) & Executive Decree 86/(Art. 3)]

- -Port pilots
- -Port workers
- -Ship Surveyors
- -Superintendents
- -Workers subject to the special working regime of the Panama Canal Authority.
- -Technical staff operating offshore drilling platforms or MODU; except those individuals that because of their training and qualifications, are covered by the provisions of the STCW Convention.
- -Armed personnel
- -Scientists
- -Researchers
- -Divers
- -Cadets
- -Specialist off-shore technicians, and others whose work is not part of the routine operation of the ship

The following documents are to be maintained on-board: [MMC-276/(2)]

Customer Service Center

5201 Blue Lagoon Drive, 9TH. Floor, Miami, Fl., 33126 Tel: 1 (305) 716 4116, Fax: 1 (305) 716 4117,

E-Mail:

joel@conarinagroup.com

Technical Head Office 7111 Dekadine Ct. Spring, Tx., 77379 Tel: 1 (281) 370 9363, 1 (713) 204 6380

E-Mail: tho@conarinagroup.com, houston@conarinagroup.com Page 1 of 2

International Medical Guide for Ships Medical First Aid Guide for Use in Accidents Involving Dangerous Goods International Code of Signals, Medical Section Ambient Factors in the Workplace

2. DMLC Part II Review

The Administration issues the ship specific DMLC Part I in digital format upon request from the shipowner. [MMC-269/2]

The ship specific DMLC Part I is to be used for conducting DMLC Part II reviews and Onboard Inspections.

3. Inspection and Certification

Upon satisfactory completion of the on board inspection, the DMLC Part II shall be signed and stamped, and the Maritime Labour Certificate (MLC) shall be issued valid for five (5) years from the date of completion of the inspection. [MMC 269/(9 & 10)]

Shipowners of vessels with a gross tonnage of 200 to 499 ITC, engaged in international voyages or voyages between ports, may request certification. The requirements relative to obtaining a DMLC Part I from the Administration, conducting a DMLC Part II review with subsequent onboard inspection. Upon successful completion a MLC may be issued. [MMC-269/(6)]

REFERENCES:

MLC - Panama

ATTACHMENTS: No.

Kindest Regards,

Cosmin Bozenovici Naval Architect - Conarina Technical Head Office

Customer Service Center

5201 Blue Lagoon Drive, 9TH. Floor, Miami, Fl., 33126 Tel: 1 (305) 716 4116, Fax: 1 (305) 716 4117,

E-Mail:

joel@conarinagroup.com

Technical Head Office 7111 Dekadine Ct. Spring, Tx., 77379 Tel: 1 (281) 370 9363, 1 (713) 204 6380

E-Mail: tho@conarinagroup.com, houston@conarinagroup.com Page 2 of 2