



TECHNICAL CIRCULAR No. 401 of 09th March 2017


To: All Surveyors/Auditors

Applicable to flag: All Flags

Class Special Survey

Reference: **CONARINA Procedures**

Special Survey Interval, Drydock, Tailshaft survey.



Docking Survey

- Two drydockings every five years period with interval between drydockings not exceeding three years.
- Drydocking is part of Special Survey

Customer Service Center

5201 Blue Lagoon Drive, 9TH. Floor,
Miami, Fl., 33126
Tel: 1 (305) 716 4116,
Fax: 1 (305) 716 4117,
E-Mail:

joel@conarinagroup.com

Technical Head Office

7111 Dekadine Ct.
Spring, Tx., 77379
Tel: 1 (832) 451 0185,
1 (713) 204 6380

E-Mail: cbozenovici@vcmaritime.com

- Intermediate Drydocking must be carried out within Intermediate Survey window.

In-Water Survey (UWILD) in lieu of docking survey

- An In-water survey (UWILD) is allowed at Intermediate Survey depending on type, age and previous history of the vessel

Tailshaft Survey

- Different intervals and different survey requirements depending on the type of arrangement
- Extensions to the Survey interval are possible
- Requirements for allowable bearing wear (measures taken at drydocking interval)

Boiler Survey

- Different requirements depending on the service (propulsion or auxiliaries)
- Propulsion Boiler intervals: two surveys during each 5-year Special Survey period (one in conjunction with the Special Survey, interval between any two not to exceed 36 months.
- Auxiliary Boilers subjected to annual internal and external examination.

REFERENCES:

- IMO DOCUMENTS

ATTACHMENTS: No.

Kindest Regards,
Cosmin Bozenovici
Naval Architect – Conarina Technical Head Office

Customer Service Center

5201 Blue Lagoon Drive, 9TH. Floor,
Miami, Fl., 33126
Tel: 1 (305) 716 4116,
Fax: 1 (305) 716 4117,
E-Mail:

joel@conarinagroup.com

Technical Head Office

7111 Dekadine Ct.
Spring, Tx., 77379
Tel: 1 (832) 451 0185,
1 (713) 204 6380

E-Mail: cbozenovici@vcmaritime.com